


Oxgangs Primary School



1. Lower roof fixings to be changed to stainless steel.
2. New fixings were installed on Sunday 18th March.
3. Lead needs fixed into the raggle and a new Polysulphide joint.
4. Open areas of cladding, and birds nest present.
5. New sill fixings required.
6. New Tech screws required.
7. New Tech screws were installed on Sunday 18th March.
8. Missing section of cladding.
9. New Tech screws required.
10. New fixings installed on Sunday 18th March; however, mild steel needs to be changed.
11. Open joints require to be sealed.

1.



2.



3.



4.



5.



6.



7.



8.



9.



10.



11.

